



We Iding




Hanametal Co., Ltd

Welding

1. Explosion Welding




- Jig Setting before explosion welding



- Firing



- The surface after explosion welding (T-type) (35T * 60W * 300L)



**3.
AL
+
Cu
Welding**



- To prevent the heat radiation from the welding points, do welding after clothing with asbestos



- AL Bar & Cu Bar welded metal bar machining process

**4.
Cu
Welding**



- Sectional cutting area to test welding points



Cu welding
BAg welding
Bcup welding