

Copper Cooling Work



Hanametal Co., Ltd

Copper Jacket Manufacturing Process

1. Casting Process



- Casting process after copper melting

2. Pre-Heating Before Hot-forging



- Pre-Heating / Hot-forging Processes

3. Hot Forging process



4. Forming After Forging




- Finished products after forging

**5.
Flow
test**



- Water flow test

**6.
Complete
Sets**



- Cooling Plant Sets